

348

27th January 2009

Diver: SAM BAXTER

DIVE: 14M 65 minutes

Chain needs replacing between
drums NO ① & NO ② 20M length

Chain missing sections between
drums ②⑤ & ②⑥ approx 2M

Chain missing sections between
drums ②④ & ②⑤ approx 10M
length, when the chain
drops over the reef edge
from 4m depth to 7m depth.

349

Divers

Dive

But

Just

cut

2009

349

11th July 2009

Divers: SAM BAXTON, Russell STANDISH

Dive: 14M 50 minutes

Bucket of Chan missing.

Turtle, Fiddler Ray, Bull Ray,

Cat fish and many nudibranchs.

men
get
man

men
M

upth.

350

Divers: Sam Baxton, Russell Stanovich,
Pete Howans, John Nowis

Dive: 52 minutes 13.9 M.

Chain allegedly stolen ^{was} ~~the~~ ^{located} when we started the
dive. Two buckets of chain.

Four divers, a would be
dive!

Chain replaced between (25) (24)

(23) & (22). No 22 label found
shackled on chain between (23)
& (24).

Chain needs to be reconciled
between (1) & (2),

351

Diver

Key

Dive

Ver

Ab

for

he

the

(10)

(1)

351

8th March

2009

DIVERS: SAM BAXTON, Russell STANDISH,
KELLY HATCH, JOHN ROWE

DIVE: 34 minutes 12.7M.

Very lumpy dive. Kelly's first
shore dive. She said it was
fun. More lumps near the
beach. Chain a little away on
the sand side between (9) &
(10). Chain still missing between
(1) & (2).

(352)

12th April
2009

DIVERS: SAM BAXTER, JOHN ROWE
DIVE: 12.7 47 Minutes

Chain reconnected at (25)
Clear thought to (17).
Bucket of chain attached
to swim to (9). Lost buoyancy
control. Very poor visibility
at this location. Swam on
surface with chain to (5) left
smaller chain at (5) Took
loop chain to (2) and reconnected.
Another 10 meters of ~~these~~ chain
need to join (1) & (2).

(353)

13th April
2009

DIVOR: SNOMCGL ONLY JOAN ROWE

DIVE: 5 MINUTES

Chen rejoined at (1) & (2)
Success could be taken
up at (3)

7
ty

ted.
han

17th May 2009

(354)

DIVERS: JOHN ROWS, Russet STANDISH
SAM BAXTER

DIVER: 14.1 M 49 Minute

Sand held between (7)
(8) (9) very thick. Buoy
just above the sand line.
Some chain joined at
(9). Still a gap between
(9) & (10). Chain connected
between (11) (12) (13). Some
chain re attached

DIVE
JOH
DIVE
Che
Wh
Cos
(10).
Ov
dev
Use
the
bes
Buck

100 Jun 2009

355

DIVERS: SAM BAXTER, Mussett STANDISH,
JOHN ROWE

DIVE: 13.8M

63 minutes

Check more fuel. Cooled
up buoys between ⑦ & ⑧ -

Cooled up chain from ⑨ to
⑩.

Obtain more chain for next
dive.

Unable to throw part chain in
the bucket as the left bag
broke the bucket is now handle
Bucket left at the entrance.

8th Jan 2009

(356)

DIVERS: SAM BAXTER, Russell STANDISH
JOHN ROWE

DIVE: 55 minutes 14.6M

Bucket of Chain was put into
two buckets. Buckets taken to
⑨. 8 metres of Chain was extracted
from the sand with the end
of two lift bags. Chain again
between ⑨ & ⑩.

Chain also replaced between
⑫ - ⑬.

Chain needs to be re-set between
⑬ & ⑭ - Allocate to
original position across the
helf?

14th

DIVER

KELL

DIVE

DRUM

NOT

WELL

DEE

TO

14th June 2009

(357)

DIVERS: SAM BAXTER, MURIEL STANDISH,
KELLY HATCH, JOHN ROWS

DIVE: 55 minutes 14.2 M.

DRUM (13) released - String
not long enough to count
was (14) some other sort.
Ool drum (13) wound on
to reef edge.

(358)

288/2009


DIVERS: SAM BAXTER, JOHN ROWS

DIVE: 11.17 67 minutes.

Rearranging tank between

(10) - (11) - (12) - (13) - (14)

(12) - (13) relocated to original position. Chain lifted up to top of reef and reel loaded to (14). Core before (11) < (10) some chain placed in position as follows



More chain required.

2009

12th July 2009

(359)

DIVERS: SAN BAXTON, JOHN ROLLO
MUSSET STAN OISH.

DIVE: 12.317 63 minutes

MASTER & COMMANDER: Peter Howland

First boat dive with
 "The Case of the Chen" Ministry
 Bacter on hand to photograph
 the occasion. Peter drove
 the boat. Chen dropped at
 location. Should have been
 left in buckets. Buoy to
 remain using diving reel.
 Left boy sent back up.
 Peter fell out of the boat.
 Swell up and three of
 us consisted Peter back in.
 Not a top firing a dive
 even though it took longer
 to get ready. One bucket of
 Chen left behind. Red & white
 cord really tangled up in tree.
 Reconnected. Three dives together
 Chen from (9) survey to row
 (10). with Chen between (11) - (12).
 Jump to (14) -

(360)

3rd August 2009

DIVONS: SA07 BAXTON

DIVE : 14M 55 Minutes

Remainder dive followed
Chai clockwise. Made a
couple of notes that were
broken. Dug out several
sections of burner then
from draws 20/21/22.

Clean up a few
burners. Red cord temporary
connection broken. Suggest
that get fixed next dive.

Agree that suggest we do
another full circuit dive
and make all sections of
the then with a quantity
noting to see which
sections are priority for
a replacement.
fiddler ray on board.

2009

(361)

Jobs August 2009

Divers: JOHN ROWLS

Dive: 11.6.M 64 minutes

Retired from Police service!
Clean gutters so go diving!

Perfect water. Check out

Chain (9) - (10) - (11) - (12) - (13) - (14)

Chain submerged at (9). 3

drums still out of position.

between (10) - (12). Chain connected

(14) (13) - Red cord snagged on

helf. Chain dragged from

drum to (12) Part joined

Nil chain from (11) - (9) -

submerged from (9) - (10)

Red cord recovered in a

tangled mess!

Move three drums! Next

dive. Move chain

(362)

21st August 2001

Divors: John Rowe

DIVE: 11.7 meters

55 minutes

Moved three drums
into new position. Pump
connected chain with
new drums. Used more
chain to ~~left~~ connect
with (9) as existing chain
badly ~~connected~~ corroded.
and also submerged in
sand. Chain lifted from
sand

363

23rd August
1909

Divers: John Rowe, Sam Boster,
Nussel Starbik

Miles & Companion: Peter Howard.

Bucket of chain, big left
bag taken out in boat.

Nussel & Sam attempted
to get chain out of
sand between (7) - (8)

Used a whole tank to
fill bag. Managed to get
about 4 meters out of
the sand. John Rowe recombed
chain (9) - (10). attempted to
remove old chain by hand
but too heavy. Bucket &
Left bag required.

(364)

25th August
2009

Divers: John Rowe. Russell
Stendil.

DIVE: 10.1. MUMS 43 minutes

Chain counted to (9), (10),

(11), (12), (13), (14), (15) -

Still too tight. Need
to adjust next dive

(365)

26th August
2009

Divers: J. Name,
Runeel Stordvik, Sam
Baker.

Divs: 12.2 metres 50 minutes

Stream Chan' out. Reaccounted

(10), (11), (12)

(366)

27th August
2009

Divers: John Rowe, Sam Baxter
Russell Starbuck

Divs. 14.3M 60 minutes.

Reduced tension in chain
by re-adding chain in
reasonable condition checked
all drum numbers.

Only Drums (3), (4), (5), (6)

(22), (23), (25)
Could not locate (7) - (8)
drums.

Chain needs repleg at
(19) - (20) - (21) - (22).

More chain needed.

~~(367)~~

~~27th August
2009~~

~~Divers: JOHN ROWE, SAM BAXTER~~

(368)

Dive

Dive

John

(15)

check

(22)

re-

see

re-

to

re-

Ne

on

He

for

on

li

fr

st.

~~368~~ (367)

240 September
2009

Divers: JOHN ROWS, SAM BAXTER

DIVE: 46.0 minutes 14.0 meters

John a bucket of chain to
(15) & rejoined to (16). Checked
chain from (17), (18), (19), (20), (21),
(22) - some stretchers need
replacing. Sam says chain
south of the deep needs
replacing. Check out. I
through chain (Sam) needed
replacing from (17) → on way
removed a small crown
out section.

New numbers put to Jimmie
for engraving. Chain purchased
for 3/18/09 from LB - all
lift bags, buoys, & rope
transferred to 4A Tragalwood
St. Brounle.

(368)

September 4
2009.

DIVERS: SAM BAXTER, JOHN NOUS

DIVE: 60 minutes

Checked out entire trail
Trail almost complete

Chain still covered
under sand. between

(6) → (5). Liam suggests
trail go past cave. This

will happen. More chain
required. Move start

down at (3) to new
location. Some chain spare
at (6).

(369)

19/10/2009

DIVERS: JOE AUSTIN SAM BAXTER

(DIVE)

18M.

50 minutes

Conducted a recess dive
of the chair, sharphead
broken sections (23) - (24)

(370)

(371)

13.1 47 minutes. 10/12/2009

Divens: RICHARD VEEVERS, RUSSELL
STANDISH, JOHN NOLLO, STEVE KUH.

DIVE Steve pulled out first
dive in 10 years! Relocated

(6) & (7) to be searched
wind cave. Big Woven
followed us. Also hatched
by accident next day

(372)

Divens: RUSSELL STANDISH
SAM BAXTER

DIVE: 45 minutes 15 M

Circuit of Chan, connected.
broken links. Several flat heads
seen. Chan obscured but was
(15) - (16) - (17) More buoys.

(370)

Div

Div

W

1

C

11th November
2009.

370

Divions: JOHN ROWS.

Divs: Post in Leanne's drive
with ABC Catalyst

13.1 meters

22 minutes.

Circuit only

(373) Diver: SAM BAXTER 24/12/09

(374)

DIVE: 15m 50 minutes

Cleared several buoys
Buoys also needed. Net was

(9) - (12) covered by sand

Di
J
Di
o
o
m
J
S
co
m